

IN THE SPECIFICATION:

Page 7, paragraph [0024], line 4 please delete reference numeral “64” following “triangular ribs” and insert therefor – 66 – as noted below.

[0024] The vehicle seat assembly 14 also includes a mounting bracket, generally indicated at 60. In the embodiment shown, the mounting bracket 60 is substantially L-shaped with a first planar member 62 and a second planar member 64 extending at a 90° angle therefrom. A plurality of triangular ribs ~~[[64]]~~ 66 extends between the first planar member 62 and second planar member 64 to thereby reinforce the attachment between the first planar member 62 and the second planar member 64. Also, two apertures 68 extend through opposing corners of the second planar member 64. The first planar member 62 defines a first surface 70 on a side opposite to that of the second planar member 64. Furthermore, a hollow tube 72 extends upward from a side of the first planar member 62 opposite to that of the first surface 70.